Button Description



4 adjustable circling ranges

I Automatic turn off after working 10min
(S:Slow Mode F:Fast Mode)

II Automatic turn off after working for 12 hours with switch on.
Laser would automatic turn off after 10min andautomatic turn on every 2 hours
(S :Slow Mode F :Fast Mode)

M Manual Mode
(Turn off actumatically after 20min)

ON/OFF